



THERMALLY BROKEN SUBFRAME
 BOTTOM WIND LOAD ANCHOR SECTION DETAIL

ULTRA SYSTEM
DATE:
NOTES:
SCALE: 1:1
TITLE:
SHEET: