


THERMALLY BROKEN SUBFRAME
 LAP JOINT CORNER DETAIL



KERF SYSTEM
DATE:
NOTES:
SCALE: 1:1
TITLE:
SHEET: