



THERMALLY BROKEN SUBFRAME
 BOTTOM WIND LOAD ANCHOR SECTION DETAIL

MECHANICAL KERF SYSTEM

DATE:

NOTES:

SCALE: 1:1

TITLE:

SHEET: