

THERMALLY BROKEN SUBFRAME
 BOTTOM WIND LOAD ANCHOR SECTION DETAIL

